




Ordering spares / Ersatzteil - Regelung / Pièces de rechange / Parti di ricambio / Lista de recambios / Onderdelen bestellen (NL/B) / Κωδικοί Ανταλλακτικών / Bestilling af reservedele / Beställning av reservdelar / Bestilling av reservedeler / Резервни части / Запчасти / Części zapasowe / Piese de schimb / Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezerves daļas / Náhradní díly / Náhradné diely / Yedek parça siparişi / Nadomestni deli

XX = AA, AD,

- 1 - B 961852 XX
- 2 - A 963751 NU
- 3 - B 961386 XX
- 4 - B 961387 NU
- 5 - A 861181 NU
- 6 - A 861156 NU
- 7 - B 960645 NU
- 8 - B 960646 AA
- 9 - B 961346 NU
- 10 - A 960537 XX
- 11 - B 961283 XX
- 12 - B 960583 NU
- 13 - B 961326 NU
- 14 - B 961389 XX
- 15 - B 961233 NU
- 16 - B 960241 XX





CERABASE




Ideal Standard















08.2022 / B565296

B D594 ..



Ideal Standard International NV
Corporate Village – Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium
<http://www.idealstandardinternational.com>





P 0,3 MPa 3 bar	T °C	Snowflake	0	1	2	3	4	5
			°C	°C	°C	°C	°C	°C
50°C	15°C		50	49	44	40	35	33
65°C	15°C		65	63	57	50	44	40
85°C	15°C		85	83	74	64	56	50

P bar	MAX. 10 0,5	5 1	Thumbs up	Q (3 bar)
T °C	MAX. 80	65 40	Thumbs up	l/min
				20 13