




Ordering spares / Ersatzteil - Regelung / Pièces de rechange / Parti di ricambio / Lista de recambios / Onderdelen bestellen (NL/B) / Κωδικός Ανταλλακτικών / Bestilling af reservedele / Beställning av reservdelar / Bestilling av reservedeler / Резервни части / Запчасти / Części zarasowe / Piese de schimb / Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezerves daļas / Náhradní díly / Náhradné diely / Yedek parça siparişi / Nadomestni deli / Pjese kembimi

XX = AA, AD, .....


- 1 - B 961560 XX
- 3 - B 964696 NU
- 4 - B 964697 XX
- 5 - B 961474 NU
- 6 - B 961475 NU
- 8 - B 961383 XX
- 9 - B 960712 XX
- 10 - B 964702 NU
- 11 - S 8803 XX
- 11a - B 961096 NU
- 12 - A 963600 NU
- 13 - B 960624 XX
- 14 - B 964902 XX




**Vidima®**




**SEVA S**

09.2018 / B665878



Ideal Standard International NV  
Corporate Village – Gent Building  
Da Vincilaan 2  
1935 Zaventem  
Belgium  
<http://www.idealstandardinternational.com>





	P	bar					Q (3 bar)
	T	°C					l/min
							5
							9